Notices of Violation Issued February 2016

Nov #	Facility	Location	Source Of Violation	Self Reported	Violation Issued	Rule
10860	Via Real, 4290 (MVFF) - Chevron	Carpinteria	Missing gasket on fill-tube		2/1/2016	206/316
10895	Platform Heritage - ExxonMobil	OCS	Failed to meet CO limit during performance testing	x	2/2/2016	206
10896	Donovan Rd., 740 E. (MVFF)	Santa Maria	Failed to submit transfer of ownership		2/18/2016	203/206
10897	Betteravia Rd., 1155 E. (MVFF) - Valley Pacific Petroleum Services, Inc.	Santa Maria	Failed to submit 2014 Annual Report		2/18/2016	206
10905	Hollister Ave., 4801 (MVFF) - Circle K	Goleta	Vapor Recovery System Compliance Test, Initial Failures		2/4/2016	206/316
10966	2822 Ballard Canyon Rd.	Solvang	Burned on a no burn day with non-compliant materials		2/17/2016	401
10980	Byron Vineyard & Winery	Santa Maria	Installed Fermentation Tanks without approval		2/19/2016	206
10982	Las Positas Rd., 2299 (CSC) - Circle K	Santa Barbara	Failed to meet ROC destruction efficiency	x	2/25/2016	206

Penalty Settlement Payments Received February 2016

Nov #	Facility	Location	Source Of Violation	Violation Issued	Rule	Date Paid	Total Penalty Received
10975	The Pictsweet Company	Santa Maria	Failed to submit 2014 Annual Report, maintain records, and calibrate fuel meter	10/22/2015	206	2/1/2016	$500
10957	Flores Auto Body	Santa Barbara	Failed to submit 2014 Annual Report	10/20/2015	206	2/2/2016	$500

$1,000